



# higher education & training

Department:  
Higher Education and Training  
**REPUBLIC OF SOUTH AFRICA**

**T480(E)(A6)T  
APRIL EXAMINATION**

**NATIONAL CERTIFICATE**

**ELECTROTECHNICS N5**

**(8080085)**

**6 April 2016 (X-Paper)  
09:00–12:00**

**Calculators may be used.**

**This question paper consists of 5 pages and 1 formula sheet of 2 pages.**

**DEPARTMENT OF HIGHER EDUCATION AND TRAINING**  
**REPUBLIC OF SOUTH AFRICA**  
NATIONAL CERTIFICATE  
ELECTROTECHNICS N5  
TIME: 3 HOURS  
MARKS: 100

---

**INSTRUCTIONS AND INFORMATION**

1. Answer ALL the questions.
  2. Read ALL the questions carefully.
  3. Number the answers according to the numbering system used in this question paper.
  4. Write neatly and legibly.
-

**QUESTION 1**

- 1.1 State TWO methods of changing the direction of a DC machine. (2)
- 1.2 Where are the compensating windings situated and how are they connected? (2)
- 1.3. The number of series turns per pole required on a 355 kW long shunt compound generator must be determined to enable it to maintain a constant voltage at 580 V, between no-load and full-load. Without any series winding, it is found that the shunt current has to be 6 A on no-load and 7,5 A on full-load, to maintain the voltage constant at 580 V. Number of turns per pole on the shunt winding is 2 100.
- 1.3.1 Calculate the demagnetising and cross-magnetising ampere-turns per pole.
- 1.3.2 If the series coils were wound with 12 turns per pole and had a total resistance of 0,08  $\Omega$ , determine the value of diverter resistance that would be required to give level compounding. (2 × 5) (10)
- 1.4 A 625 V, 35 kW, four-pole DC motor has a wave-wound armature with 900 conductors and the commutator has 180 segments. The full-load efficiency is 85% and the shunt current is 2,25 A. The brushes are shifted backwards through 1,5 segments from the geometrical neutral axis .
- Calculate the demagnetising and cross-magnetising ampere-turns per pole. (6)  
[20]

**QUESTION 2**

- 2.1 The voltage across a certain circuit element is  $v(t) = 800 \sin(314 t + 30^\circ)$  V. The current flowing in this element is  $i(t) = 8 \sin(314 t + 30^\circ)$  A.
- Determine :
- 2.1.1 The nature and magnitude of this element.
- 2.1.2 The time period of the waveform. (2 × 3) (6)
- 2.2 A circuit consisting of a coil with an inductance of 140  $\mu$ H and a resistance of 8,25  $\Omega$  is connected in parallel with a variable capacitor. This combination is then connected in series with a resistor of 7300  $\Omega$  across a 380 V supply having a frequency of 1 MHz.
- Calculate :
- 2.2.1 The capacitance of the capacitor required to give resonance. (3)
- 2.2.2 The impedance of the parallel circuit. (2)
- 2.2.3 The current in each branch of the parallel circuit. (9)  
[20]

**QUESTION 3**

- 3.1 Name THREE methods of reducing leakage flux in transformers. (3)
- 3.2 A 24 kVA, 3 200/800 V single-phase transformer, operating at no-load has the following resistances and leakage reactances.
- |                     |            |               |           |               |
|---------------------|------------|---------------|-----------|---------------|
| Primary winding :   | Resistance | 8,4 $\Omega$  | Reactance | 14,4 $\Omega$ |
| Secondary winding : | Resistance | 0,75 $\Omega$ | Reactance | 1,5 $\Omega$  |
- Calculate the secondary voltage at full-load, with a power factor of 0,8 lagging, when the primary voltage remains constant. (7)
- 3.3 Three similar inductors, with a resistance of 29  $\Omega$  each and an inductance of 0,038H are connected in delta to a three-phase, 535 V, 50 Hz sinusoidal supply.
- Calculate :
- 3.3.1 The value of the line current. (6)
- 3.3.2 Power factor. (2)
- 3.3.3 Power input to the circuit. (2)
- [20]**

**QUESTION 4**

- 4.1 The input power to a 2 950 V three-phase delta-connected induction motor is 135 kW. The power factor of the motor is 0,85 lagging.
- Calculate:
- 4.1.1 The line and phase currents (2)
- 4.1.2 Input power readings on the two watt-meters (4)
- 4.1.3 kVA rating of the motor (2)
- 4.2 A three-phase transmission line supplies a 1,73 MW star-connected load, having a power factor of 0,75 lagging at a line voltage of 35 kV. The line has a resistance of 85  $\Omega$  per phase and an inductive reactance of 155  $\Omega$  per phase.
- Calculate :
- 4.2.1 Voltage (line) at the sending end (5)
- 4.2.2 The per-unit regulation (2)
- 4.2.3 Efficiency of the line (5)
- [20]**

**QUESTION 5**

5.1 Briefly explain the term *hunting* or phase swinging with reference to synchronous motors. (2)

5.2 A three-phase slip-ring induction motor gives a reading of 95 V across the slip-rings on open circuit with normal stator voltage applied. The rotor is star-connected and has an impedance of  $0,7 + j 9 \Omega$  per phase.

Calculate the impedance:

5.2.1 At standstill with the slip-rings joined to a star-connected starter with a phase impedance of  $4 + j 7 \Omega$ . (4)

5.2.2 When running normally with 5 % slip. (2)

5.3 A three-phase induction motor with a star-connected rotor, has an induced EMF of 145 V between slip-rings at standstill on open circuit. The rotor resistance and reactance per phase at standstill is 1, 25  $\Omega$  and 6, 75  $\Omega$  respectively.

Calculate the following when the slip-rings are short-circuited :

5.3.1 The rotor starting current per phase. (4)

5.3.2 The power factor. (2)

5.4 A three-phase star-connected alternator, driven at 1 200 rev/min. is required to generate a line voltage of 885 V at 60 Hz. on open circuit. Assume full-pitched coils and the stator has 8 slots per pole per phase and 6 conductors per slot. ( $k_d = 0,96$ )

Calculate :

5.4.1 The number of poles. (2)

5.4.2 The useful flux per pole. (4)

[20]

**TOTAL: 100**

**ELECTROTECHNICS N5****FORMULA SHEET**

Armature ampere-turns/pole  
Ankerampèrewindings/pool

$$= \frac{1}{2} \cdot \frac{I_a}{C} \cdot \frac{Z}{2P}$$

$$E = V \pm I_a R_a$$

$$E = \frac{2pNZ\Phi}{60c}$$

$$T = 0,318 \frac{I_a}{c} ZP\Phi$$

$$k = n \sqrt{\frac{R_1}{r_m}}$$

$$r_1 = R_1 \left[ \frac{k-1}{k} \right]$$

$$r_1 = R_s \frac{1-y}{1-y^m}$$

$$R_1 = bR_1 (k-1) \times \frac{1-b^n}{1-b} + r_m$$

$$y = \frac{I_2}{I_1}$$

$$r_1 = bR_1 (k-1)$$

$$\frac{E_1}{E_2} = \frac{K\Phi_1 N_1}{K\Phi_2 N_2}$$

$$\frac{T_1}{T_2} = \frac{K\Phi_1 I_{a1}}{K\Phi_2 I_{a2}}$$

$$I_{ave/gem} = \frac{i_1 + i_2 + i_3 + \dots + i_n}{n}$$

$$I_{rms/wgk} = \sqrt{\frac{i_1^2 + i_2^2 + i_3^2 + \dots + i_n^2}{n}}$$

$$f = \frac{1}{2\pi\sqrt{LC}}$$

$$f = \frac{1}{2\pi L} \sqrt{\frac{L}{C} - R^2}$$

$$P = \sqrt{3} I_L V_L \cos \phi$$

$$P_1 = V_L I_L \cos (30 - \phi)$$

$$P_2 = V_L I_L \cos (30 + \phi)$$

$$\tan \phi = \frac{\sqrt{3} (P_2 - P_1)}{(P_2 + P_1)}$$

% Voltage regulation  
% Spanningsreëling

$$= I_1 \frac{(R_e \cos \phi \pm X_e \sin \phi)}{v_1} \times \frac{100}{1}$$

$$Z_e = \sqrt{R_e^2 + X_e^2}$$

$$\% Z_e = \frac{I Z_e}{V} \times \frac{100}{1}$$

$$S_1 = S \frac{Z_2}{Z_1 + Z_2}$$

$$E = 2,222 k_d k_p Z \Phi f$$

$$I_r = \frac{E_r}{Z_r}$$

$$E_o = V_p \frac{Z_r}{Z_s}$$

$$\cos \phi_r = \frac{R}{Z_r}$$

$$s = \frac{2\pi T (n_s - n_r)}{2\pi T n_s}$$

$$L = 0,05 + 0,2 \text{ Lin } \frac{d}{r}$$

$$C = \frac{1}{36 \text{ Lin } \frac{d-r}{r}}$$

$$C = \frac{1}{18 \text{ Lin } \frac{de}{r}}$$

% Regulation  
% Regulering

$$= \frac{V_s - V_R}{V_R} \times \frac{100}{1}$$